


# Long Creek Watershed Tour 2005

Supplemental Handouts Containing Photographs,  
Maps, and Data Related to the Conditions  
of the Stream


PART 1



**Reference:**

Seeley, R. A. and B. D. Valle. 1983. Clark's Pond Study. South Portland Planning Dept., South Portland, Maine.






Red Brook – reference site




# Long Creek – mainstem - upper


(above Spring St.) [1]



(golf course  
stream section) [2]




(in woods above I-95;  
reasonably good habitat  
conditions) [3]






# Long Creek – mainstem – lower - (above Foden Rd.)




channel degradation





1983 – looking downstream; channel alterations



2000 – looking upstream; loss of floodplain


Long Creek – mainstem – lower  
(below Foden Rd.)



## Long Creek – south branch - lower




trash (e.g., shopping carts, tires, etc.); debris; channel degradation





## Long Creek – north branch - lower



stormwater inputs; trash

